

VISUAL INSPECTION SUMMARY REPORT

Optronics S.A. de C.V. FiberChek2™


May 30, 2022, 7:40:12 PM
 EQ G LINEA 4 , Jumper LC/UPC-LC/UPC Monomodo 9/125 Duplex de
 2m Riser de 2mm

© 2008 Westover Scientific, Inc.
<http://www.westoverfiber.com>

Inspection Result / Fiber Name:	
File Name:	S100757-23221502A1
Serial Number:	
Lot Number:	
IL:	<0.20 dB
RL:	>55.00 dB
Profile:	SM, Post Polish (IEC-61300-3-35 Table 3)

*****PASS*****

Inspection Summary:							
Zone Name	Diameter (μ)		Defects			Scratches	
	Inner	Outer	Result	Count	Area (μ ²)	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	2	2.01802	PASS	0
Zone E	250	1000	PASS	3	2.01802	PASS	0
Epoxy Gap:	PASS		Fiber Type:	Simplex		Core Size:	9



VISUAL INSPECTION SUMMARY REPORT

Optronics S.A. de C.V. FiberChek2™


May 30, 2022, 7:43:58 PM
 EQ G LINEA 4 , Jumper LC/UPC-LC/UPC Monomodo 9/125 Duplex de
 2m Riser de 2mm

© 2008 Westover Scientific, Inc.
<http://www.westoverfiber.com>

Inspection Result / Fiber Name:	
File Name:	S100757-23221502B1
Serial Number:	
Lot Number:	
IL:	<0.20 dB
RL:	>55.00 dB
Profile:	SM, Post Polish (IEC-61300-3-35 Table 3)

*****PASS*****

Inspection Summary:							
Zone Name	Diameter (μ)		Defects			Scratches	
	Inner	Outer	Result	Count	Area (μ ²)	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	2	2.01802	PASS	0
Zone E	250	1000	PASS	3	2.24225	PASS	0
Epoxy Gap:	PASS		Fiber Type:	Simplex		Core Size:	9



VISUAL INSPECTION SUMMARY REPORT

Optronics S.A. de C.V. FiberChek2™


May 30, 2022, 7:41:46 PM
 EQ G LINEA 4 , Jumper LC/UPC-LC/UPC Monomodo 9/125 Duplex de
 2m Riser de 2mm

© 2008 Westover Scientific, Inc.
<http://www.westoverfiber.com>

Inspection Result / Fiber Name:	
File Name:	S100757-23221502B2
Serial Number:	
Lot Number:	
IL:	<0.20 dB
RL:	>55.00 dB
Profile:	SM, Post Polish (IEC-61300-3-35 Table 3)

*****PASS*****

Inspection Summary:							
Zone Name	Diameter (μ)		Defects			Scratches	
	Inner	Outer	Result	Count	Area (μ ²)	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	2	2.01802	PASS	0
Zone E	250	1000	PASS	2	1.7938	PASS	0
Epoxy Gap:	PASS		Fiber Type:	Simplex		Core Size:	9



VISUAL INSPECTION SUMMARY REPORT

Optronics S.A. de C.V. FiberChek2™

May 30, 2022, 7:40:55 PM
 EQ G LINEA 4 , Jumper LC/UPC-LC/UPC Monomodo 9/125 Duplex de
 2m Riser de 2mm

© 2008 Westover Scientific, Inc.
<http://www.westoverfiber.com>

Inspection Result / Fiber Name:	
File Name:	S100757-23221502A2
Serial Number:	
Lot Number:	
IL:	<0.20 dB
RL:	>55.00 dB
Profile:	SM, Post Polish (IEC-61300-3-35 Table 3)

PASS

Inspection Summary:							
Zone Name	Diameter (μ)		Defects			Scratches	
	Inner	Outer	Result	Count	Area (μ ²)	Result	Count
Zone A	0	25	PASS	0	0	PASS	0
Zone B	25	120	PASS	0	0	PASS	0
Zone C	120	130	PASS	0	0	PASS	0
Zone D	130	250	PASS	2	2.01802	PASS	0
Zone E	250	1000	PASS	2	1.56957	PASS	0
Epoxy Gap:	PASS		Fiber Type:	Simplex		Core Size:	9

